



Ground

R35 3 vdc to ground when system is on

F2 48 vdc on either side to ground

J1 pin 1 48 vdc to ground

J1 pin 2 1 vdc to ground

R14 Y Axis direction change