



** Paper - Die Cuts With A View 60-80 pound acid free

** Stencil - Grafix

Paper - 1:47

Wood - 1:54

Open Demonstration File	(already scanned and prepared image)
Notes:	trace for cutting is hairline and red - after tracing, the vector outline left by tracing can be changed to hairline thin and red for cutting. The fill is removed for cutting by turning it off in CorelDRAW!
	Generally, a scanning demonstration is not done because it is a common process and it distracts from the VersaLaser presentation. Also, the raw traced files have many extra points which slow down laser cutting dramatically if they are not edited out of the traced image. For low volume production, a raw traced image is fine. For higher volume production, cleaning up a traced image is worth the editing time.
Install Cutting Table	demonstration can be done without cutting table to demonstrate the advantage of the cutting table (less smoke damage on the back)
Place Material	Place one sheet/thickness of material (paper, wood, mat board, stencil plastic or fabric) onto top left corner of cutting table
Print Artwork	- select material and material thickness - start job
Notes:	Material Information:
a.	Paper Diecutswithaview.com
b.	Stencil Plastic Grafix Plastics (grafixplastics.com)
c.	Wood
d.	Mat Board Local purchase
e.	Fabric