

ERROR: USB No Air Device Detected.

Power system down, remove back electronics cover, disconnect the USB cable from air box to Motion Control board. Reconnect and power up.

No USB Air Device Found. Move USB connector (dark gray) to USB port on mother board.

It sounds like we physically lost the USB connection. I doubt air pressure could be the problem. More likely:

- 1) Bad USB cable (or cable connector) to the Air Unit.
- 2) The USB cable just isn't plugged in, for some reason.
- 3) Possibly, a power supply issue.
- 4) Does red-buttoning completely down, then back on again resolve the problem?

Miles