


I measured voltage in this point of 4 power supply.

When 4 plugs were unplugged and laser was irradiated, voltage dropped to about 33V.

I unplugged these plugs and measured the voltage of 4 power supply.



When 4 plugs were unplugged and laser was irradiated, this cooling fan became slow-down.